

Reference	SSM72519
Models	Range Rover Evoque / L538
Title	Vehicle fails to restart automatically after eco stop, P162F DTC stored. 2.0GTDi engine only.
Category	Engine
Last modified	16-Nov-2015 00:00:00
Symptom	499000 Basic Engine
Content	<p><u>Issue:</u> Vehicle does not automatically restart when required to do so, after entering eco-stop. P162F DTC stored. Starter Motor disabled - Engine crank time too long.</p> <p><u>Cause:</u> Sub-optimal PCM software on vehicles within the Q511 campaign Vin range.</p> <p><u>Action:</u> Check the status of Q511 campaign.</p> <ul style="list-style-type: none">• If Q511 campaign is open, please complete Q511 and retest vehicle. If fault persists proceed with standard diagnosis, Refer to Topix DTC index and perform all tests related to DTC P162F.• If Q511 campaign is already complete, please proceed with standard diagnosis. Refer to Topix DTC index and perform all tests related to DTC P162F. Raise an EPQR once repair is complete.• If Q511 campaign not applicable to this vehicle, Please proceed with standard diagnosis, Refer to Topix DTC index and perform all tests related to DTC P162F. Raise an EPQR once repair is complete. <p><u>Note:</u> If you are unable to repair the vehicle, please raise a TA providing evidence to support all previous diagnosis carried out</p>