
Reference	SSM72522
Models	LR2 / L359 Range Rover Evoque / L538
Title	L538 & L359 Halogen bulbs blown
Category	Electrical
Last modified	18-Nov-2015 00:00:00
Symptom	201000 Lighting Systems

ContentIssue:

L538 & L359 halogen bulb(s) blowing within the 12 month warranty of the bulb.
Halogen bulb - LR044458.

Cause:

LTB00841 has been temporarily removed from Topix in order to procure sufficient parts from JLR suppliers.

Action:

Replace bulb, if the car is:

- Within 12 months of warranty sold date, or
- If the last bulb replaced is within 12 months.

Please submit an EPQR for future reference.

JLR will re-issue the TSB when parts are available.