

Reference	SSM72531
Models	Discovery Sport / L550 LR2 / L359 Range Rover Evoque / L538
Title	2.0 GTDi - DTC P008A, P008B, P2542: Engine MIL illuminated in IPC: Rough Idle, Hesitation.
Category	Engine
Last modified	19-Nov-2015 00:00:00
Symptom	404000 Fuel System Concerns
Content	<p><u>Issue:</u> Symptom: - Engine MIL illuminated on IPC. Rough idle, Hesitation and/or loss of power. One or more of the following DTCs may be set in the PCM:</p> <ul style="list-style-type: none">• P008A,• P008B,• P2542. <p><u>Cause:</u> Sub-optimal PCM software calibration</p> <p><u>Action:</u> Check the status of Q511 campaign.</p> <ul style="list-style-type: none">• If Q511 campaign is open, complete Q511 and retest vehicle.• In all other cases, proceed with standard diagnosis. Refer to Topix DTC index and perform all tests related to stored DTC. <p>Note: -</p> <ul style="list-style-type: none">• Raise an EPQR once repair is complete or TA if further assistance is required.