

Reference	SSM72541
Models	Range Rover Sport / L320
Title	L320 Range Rover Sport Wheel Arch Finishers Corroded or Mis -shaped
Category	Body
Last modified	26-Nov-2015 00:00:00
Symptom	108000 Ext. Trim/Accessories
Attachments	L320 Wheel Arch Finisher.pdf (L320 Wheel Arch Finisher.pdf)

Content**Issue**

L320 Range Rover Sport Customers may report that either of or both Rear Wheel Arch Finishers have corroded or become mis-shaped – See attached photo's

Cause

Corrosion and thus structural failure of the internal aluminium carrier causes the part to distort and potentially come adrift

Action

This part was added to the vehicle as a cosmetic part and has no added benefit.

Engineering testing has confirmed that if the part is removed it has no detrimental effect to the vehicle.

With this in mind should a customer report this concern then you are asked to remove both Wheel Arch Finishers (Part No. CLB500061) to maintain a symmetrical appearance and replacement is not required.



