

Reference	SSM38303
Models	Defender / L316 LR2 / L359 LR3 / L319 Range Rover / L322 Range Rover Sport / L320
Title	Power Steering System Flushing Procedure.
Category	Chassis
Last modified	05-Jan-2015 00:00:00
Symptom	303000 Steering/Handling
Content	<p><u>Issue:</u> When completing a repair on components in the Power Assisted Steering system, debris may be found within the power steering fluid system which could lead to system contamination and a deterioration in system performance.</p> <p><u>Cause:</u> Internal debris from a suspected component malfunction may result in the power steering fluid becoming contaminated.</p> <p><u>Action:</u> After identifying and changing the steering component which caused the contamination, please follow the power steering system flushing procedure in GTR, section 211-00, General Procedures, Power Steering System Flushing. The power steering system flushing procedure SRO number is 57.15.31 It is no longer necessary to change the entire power steering system when contamination has been found.</p>