

<b>Reference</b>	SSM72088
<b>Models</b>	LR4 / L319 Range Rover / L405 Range Rover Sport / L494
<b>Title</b>	Squeak Noise When Pressing Brake Pedal
<b>Category</b>	Chassis
<b>Last modified</b>	21-Dec-2015 00:00:00
<b>Symptom</b>	301000 Service Brake System
<b>Attachments</b>	1Brake Pedal SSM Lubrication Guide.jpg (1Brake Pedal SSM Lubrication Guide.jpg)
<b>Content</b>	Issue – Squeak noise when brake pedal is operated.

Cause – Brake light switch / brake pedal shim interaction. **NOTE:** Not all vehicles will be fitted with brake pedal shim.

Action – Apply PTFE Dry Lubricant (AC-F27 pen which is available in squeaks and rattles kit) to shim (if fitted) and brake switch plunger. Removal of the brake switch plunger is **not** required for this procedure. Once the lubricant has cured please operate the pedal to confirm the noise is no longer present.

**Attached picture shows where to lubricate.**

*Technicians - Please rate this SSM and provide comments so that future communications can be improved.*

*1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.*

*3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.*

*5 = Excellent – All required information provided to resolve the customer concern.*



