
Reference	SSM72522
Models	LR2 / L359 Range Rover Evoque / L538
Title	L538 & L359 Halogen bulbs blown
Category	Electrical
Last modified	07-Dec-2015 00:00:00
Symptom	201000 Lighting Systems
Content	<p><u>Issue:</u> L538 & L359 halogen bulb(s) blowing within the 12 month warranty of the bulb. Halogen bulb - LR044458.</p> <p><u>Cause:</u> LTB00841 has been temporarily removed from Topix in order to procure sufficient parts from JLR suppliers - parts are due to be made available to markets in week 4 of 2016, upon which, the bulletin will be released for publication.</p> <p><u>Action:</u> Continue to replace bulb(s) when blown. Please raise an EPQR if the vehicle:</p> <ul style="list-style-type: none">• Is within 12 months of warranty sold date, or• If the last bulb replaced is within 12 months. <p>The EPQR will be used for future reference i.e. back orders and warranty analysis. JLR will re-issue the TSB when parts are available.</p>