
Reference	SSM72548
Models	Discovery Sport / L550 Range Rover Evoque / L538
Title	L538 RR Evoque & L550 Discovery Sport glass run seal tuck-in and window squeak
Category	Body
Last modified	02-Dec-2015 00:00:00
Symptom	102000 Window/Glass

ContentIssue:

1. The glass run seal tucks in near the door mirror on L538
2. The glass run seal tucks in on the glass run lower channel on L550
3. Both variants produce a squeak when the window raise/lower function is operated

Cause: Glass run seal looses the flock and this increases the friction between the glass and the seal.

Action: For vehicles before:

- L538: H087649
- L550: H552127

Please replace the glass run seal with the latest level part available in MicroCat for the door glass that emits the symptoms noted above.

For any failures post these VINs, please submit an EPQR.