

---

<b>Reference</b>	SSM72550
<b>Models</b>	Range Rover / L405 Range Rover Sport / L494
<b>Title</b>	L405 / L494 Groan noise from dynamic response system during certain manoeuvres
<b>Category</b>	Chassis
<b>Last modified</b>	22-Dec-2015 00:00:00
<b>Symptom</b>	304000 Suspension System

---

**Content****Issue:**

A customer may report that during certain driving manoeuvres there is a groan noise from the suspension that lasts approximately 1 second. The main driving manoeuvres associated with this are:

1. Steering right and then hitting a bump/ridge in the road very soon after.
2. Steering to the right and then sharply steering to the left.

**Cause:**

This is caused by the fluid moving within the dynamic response valve block combined with rapid system pressure changes.

**Action:**

No action to be taken - this is the standard operation of the system.