

---

<b>Reference</b>	SSM72576
<b>Models</b>	Discovery Sport / L550
<b>Title</b>	L550 Discovery Sport Tow Hitch Assist accuracy
<b>Category</b>	Accessories
<b>Last modified</b>	23-Dec-2015 00:00:00
<b>Symptom</b>	General Accessories
<b>Attachments</b>	IMG_5523.JPG (IMG_5523.JPG)

---

**Content**      Issue: Customers are expressing concerns with the tow hitch assist accuracy.

Cause: The image overlay on the HLDF is not accurately aligned to the tow hitch (see attachment).

Action: Could you please continue to raise EPQR's to help with the investigation.

Please assist JLR engineering to identify the following:

1. Spare wheel is fitted or No spare wheel.
2. Dealer fit or Factory fit.
3. Tow Bar type fitted: -
  - 7 Seat Detachable UK & Europe
  - 7 Seat Flange UK & Europe
  - 7 Seat NAS/AUS
  - 5 Seat Flange UK & Europe
  - 5 Seat NAS
  - 5 Seat detachable UK, Europe and ROW
  - 5 Seat Electric deployable UK & Europe

Check surroundings for safety

