

GPOP - Issue Review System

Part Number: 05033313A\$

Part Description: Coolant Temperature Sensor

Issue Description: Check Engine Light (MIL) with any of the following Fault Codes: P0128, P0116, P0118, P2181. Read the date code on the Coolant Temperature Sensor. (1) If the sensor date code number is higher than date code 1222 (May 1, 2012) and (2) the Diagnostic procedure indicates that the Coolant Temperature Sensor is faulty, replace the sensor and also replace the mating engine harness connector using the connector kit, P/N 05014003AA. Return the sensor, with the connector attached, to QEC. If you have any questions, please call Tim McDonald on his cell phone @ (248) 701-9618. If you do not receive a call back within 15 minutes, Please proceed the Normal Repair.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system
