

GPOP - Issue Review System

Part Number: 05149168A\$

Part Description: Ignition Coil

Issue This TechTip applies to model years 2013 to 2014. MIL on with Coil Ionization Fault -
Description: P2302, P2305, P2308, P2311, P2314, or P2317. Prior to replacing the coil, please collect Freeze Frame data with WiTech, email the information to t1m13@chrysler.com and contact Tim McDonald on cell at (248) 701-9618. If no response to phone call received within 15 minutes, then continue with repair.

~ ~ ~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
