

## GPOP - Issue Review System

**Part Number:** 05149263A\$

**Part Description:** Sensor, Oxygen

---

**Issue Description:** Issue 1: If exhaust components are being replaced, the O2 Sensor and Exhaust Temperature Sensors should not be replaced unless there are associated diagnostics that indicate the sensor is malfunctioning. Reimbursement will not be allowed for the return of sensors which should not have been replaced. NOTE: Anti-Sieze must be applied prior to sensor re-assembly.

Issue 2: Do not replace the oxygen sensor for 2010 - 2012 model Ram Trucks without first performing Service Bulletin 25-003-13 and/or 25-004-13. In addition, until all Service Bulletin repairs have been made and the validation test has been performed, Do not install new O2 sensors.

Issue 3: Before replacing O2 sensors for P014C and/or P013A, please perform a search in TechCONNECT for additional NEW diagnostics.

~ ~  
Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

---