

GPOP - Issue Review System

Part Number: 53022372A\$, 53022263A\$, 53021726B\$, 53021728B\$

Part Description: Camshaft and Lifters

Issue 5.7L MDS engine equipped Police units (Charger, Durango, RAM 1500) that
Description: experience an engine ticking noise or misfire after an estimated 30,000 miles in service will require a camshaft and lifter inspection. If lifter rollers are seized and no longer rotating there is a potential that there is also premature camshaft lobe wear. Replacing both the camshaft and lifter components is recommended. Please contact Jose Velez for further information at (248) 431-4115.
