

GPOP - Issue Review System

Part Number: 68029261A\$

Part Description: Clutch pedal- upstop switch

Issue Description: Manual drive vehicles experiencing fault code (P0830) is related to the clutch pedal upstop switch staying "On" during normal driving. Most likely, the driver is riding the clutch pedal and not fully releasing the clutch pedal to change the clutch upstop switch state. Before replacing switch clear fault codes and test drive vehicle insuring foot is not resting on clutch pedal. If the fault code does not return inform the customers of your findings.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
