

## **GPOP - Issue Review System**

**Part Number:** 68085202A\$, 68166540A\$

**Part Description:** Knock sensor, KOP harness

---

**Issue** Before replacing a part to resolve a P0325 or P0330 code on a 2013MY/2014MY

**Description:** 3.6L JK, please contact Joseph Fasi on his cell phone at (248) 701-3690. If no response is received within 15 minutes, then continue with repair.

~ ~  
Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

---