

GPOP - Issue Review System

Part Number: 05179099A\$

Part Description: Camshaft Position Sensor

Issue If replacing this sensor due to an active or stored P0340 or P0341 fault code, please
Description: contact Christine Donegan with STAR Support Center at (866) 799-1692 ext.1257.
Instruction will be provide for returning the Cam Position Sensor via Fast Track
process. Cummins is actively investigating this fault code and requires sensors from
the field for further investigation and testing.

~ ~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP
Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or
part order inquires. Please include the Part Number (s) and Tech Tip Part
Description of the Tech Tip you are referencing for our tracking system
