

GPOP - Issue Review System

Part Number: SP070507A\$

Part Description: Spark Plug

Issue This Tech Tip applies only to model years 2012 to 2014 PF, FF, BF application with the 1.4l Turbo engine. Issues: (1) MIL on with any of the following PCM fault codes: P0300, P0301, P0302, P0303, P0304. (2) No Start due to Wet Fuel Fouling of spark plugs. Prior to replacing the spark plug please collect Freeze Frame data with WiTech, email the information to gj133@chrysler.com and contact Gary Johnston on cell at (248) 760-8415. Also, place the used spark plugs in the replacement spark plug packaging for shipment. If there is no response to the phone call within 15 minutes continue with the repair.

~ ~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
