

2011-2014 Mazda2 **LACK OF POWER AND/OR DTC P0101 AFTER INSTALLATION** **OF AN AFTERMARKET CRUISE CONTROL SYSTEM**

Some customers may complain about a lack of power and/or CHECK ENGINE LIGHT  indicator light ON

(DTC P0101 MAF sensor circuit range/performance problem) after the installation of an aftermarket cruise control system.

The aftermarket accessory may interfere with the vehicle's engine control system. Lack of power and/or DTC P0101 may be stored in PCM memory.

Remove the accessory to correct the concern.

Warranty Compliance Note

Repairs for this concern are not covered by Mazda's warranty policy.

An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication. © 2014 Mazda Motor of America, Inc.

To contribute repair tip ideas, send an e-mail to mtips@mazdausa.com or fax to (949) 442-6599. If we select your repair tip, you will receive 10,000 Reward Performance by Mazda (RPM) points for your efforts. All contributions become property of MNAO, which assumes permission to publish them without further consideration.