


MULTI-MODEL (EQUIPPED WITH IDLE CONTROL VALVE) *HIGH ENGINE IDLE SPEED*

Some customers may complain about a high engine idle speed. A stuck open idle air control valve (IAC) may be the cause.

If normal Workshop Manual diagnosis does not isolate the cause of the high engine idle, check for a stuck open IAC valve.

If the IAC valve is stuck open, replace it to correct customers concern.



An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication. © 2015 Mazda Motor of America, Inc.

To contribute repair tip ideas, send an e-mail to mtips@mazdausa.com or fax to (949) 442-6599. If we select your repair tip, you will receive 10,000 Reward Performance by Mazda (RPM) points for your efforts. All contributions become property of MNAO, which assumes permission to publish them without further consideration.