

2014-2016 Mazda3

MAZDA CONNECT "NO SIGNAL" MESSAGE IN REVERSE

Some customers may complain about the rear view monitor showing a "NO SIGNAL" message in Reverse. A poor electrical connection at connector C-16 may be the cause.

A simple disconnect and reconnect of connector C-16 may resolve the customer's concern. Connector C-16 is located at the left side of the trunk (sedan) or cargo area (hatchback). C-16 trunk connector (sedan) is shown.



An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication. © 2015 Mazda Motor of America, Inc.

To contribute repair tip ideas, send an e-mail to mtips@mazdausa.com or fax to (949) 442-6599. If we select your repair tip, you will receive 10,000 Reward Performance by Mazda (RPM) points for your efforts. All contributions become property of MNAO, which assumes permission to publish them without further consideration.