



Service Bulletin

INFORMATION

Subject: Foam And Cardboard Insert Found In Trunk During PDI


Models: 2016-2017 Chevrolet Volt

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

When performing a pre-delivery inspection you may find a piece of foam that is surrounded by a cardboard shell that is found in the vehicle during PDI. (See Photos below)





Recommendation/Instructions

This Insert is a spacer that is part of the tire Inflator kit and should be placed between the compressor assembly and the tire sealant canister. This Insert needs to be installed to prevent the damage to the contents of the bag when tightening the hold down for the Inflator kit.



Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION