



Service Bulletin

PRELIMINARY INFORMATION

Subject: Diagnostic Information For DTC P0777

Models: 2016 Chevrolet Silverado

2016 GMC Sierra

Equipped with 6.0L Engine (RPO L96) and 6L90 Automatic Transmission (RPO MYD)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Technicians may find DTC P0777 as an active or stored history code in the Transmission Control Module (TCM).

Recommendation/Instructions

Follow eSI diagnostics for DTC P0777.

If DTC P0777 cannot be duplicated while following Circuit / System Verification it is likely caused by the TCM calibration.

A TCM service calibration will be released soon to address DTC P0777, do not attempt any repairs at this time.

A bulletin will be issued when the service calibration is available.

If DTC P0777 can be duplicated while following Circuit / System Verification continue with Circuit / System Testing as published to correct the issue.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION