

Bulletin No.: PIP5399

Date: May-2016

Service Bulletin

PRELIMINARY INFORMATION

Subject: Incorrect Oil Pan Installed On Re-Manufactured HFV6 Engines

Models: 2007 Cadillac CTS

2009 Cadillac CTS and SRX

Equipped with a 3.6L LY7 HFV6 Engine

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some 3.6L LY7 re-manufactured engines built after 2/1/2016 were built with the wrong oil pan installed. Some of these engines were built with a 12638371 FWD oil pan and should have a 12592105 RWD oil pan.

Recommendation/Instructions

If you have a vehicle with this concern, replace the oil pan with the pan from the original engine (after cleaned) or a new pan if the original is unusable.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safety. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

