

45803	Some 2015-2016 F-150 vehicles built on or before 02/02/2016 may exhibit a trailer connected then trailer disconnected and/or a trailer battery not charging message displayed in the message center when no trailer is being used. To correct the concern, reprogram the Trailer Module (TRM) to the latest calibration using IDS version 98.04 or higher. Make sure you are connected to the internet when entering module programming to obtain the latest updates. Calibration files may also be obtained at <a href="http://www.motorcraftservice.com">www.motorcraftservice.com</a> . Use causal component 19H332 and applicable 12651D labor operations from Section 10 of the Service Labor Times Standards manual for reprogram only.
-------	---