

45823	Some 2017 Fusion Hybrid vehicles may exhibit a concern where the Neutral Tow selection in the instrument panel cluster message center menu is not available. A new calibration is being developed to correct this condition. Monitor OASIS for updates.
-------	---