

6/29/2016 MY16 KL

GPOP - Issue Review System

Part Number: 1SZ34AXRA\$, 1SZ34GW7A\$, 1SZ34HVGAS\$, 1SZ34JGXA\$, 1SZ34JRPA\$,
1SZ34JSCA\$, 1SZ34KBUA\$, 1SZ34KEPA\$, 1SZ34KFSA\$, 1SZ34LAUA\$,
1SZ34LDSA\$

Part Description: Exterior Door Handle

Issue Description: For KL models only; If replacing the drivers exterior door handle, please replace both the handle and cap as long as this TechTip is active. This is needed to try to root cause the entire handle for a special study.

~

____~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
