Advanced Technical Information

P0071 Is Present

9168 Binder - Advanced Technical Information

Macan (95B)

1615

Temperature Sensor Does Not Communicate via CAN;

Attention:	Macan (95B)								
Model Year:	2015-2016								
Customer Concern:	The customer observes an MIL.								
Technical Concern:	The technician is able to verify the MIL and notices fault code P0071 stored in the DME.								
Service Information:	PCNA is aware of this this issue. As background information, the fault is caused by the temperature sensor not communicating with the DME via CAN.								
	The customer solution is to update the DME software. Countermeasure software is available as of PIWIS tester version 17.400.010.								
	Be sure to enter the customer statement in the PQIS line and upload a VAL.								
	In PQIS, please code the "cause" as follows:								
	Cause Location:91680Outside-temperature sensorCause Symptom:4022Signal missing								

Dealership Distribution Routing	Service Manager	 Shop Foreman	 Service Technician	 	 	
	Asst. Manager	 Warranty Admin.	 Service Technician	 	 	

Dr. Ing. h.c. F. Porsche AG is the owner of numerous trademarks, both registered and unregistered, including without limitation the Porsche Crest®, Porsche®, Boxster®, Carrera®, Cayenne®, Caye Porsche automobiles such as, the federally registered 911 and Boxster automobiles. The third party trademarks contained herein are the properties of their respective owners. Porsche Cars North America, Inc. believes the specifications to be correct at the time of printing. Specifications, performance standards, standard equipment, options, and otherelements shown are subject to change without notice. Some options may be unavailable when a car is built. Some vehicles may be shown with non-U.S. equipment. The information contained herein is for internal authorized Porsche dealer use only and cannot be copied or distributed. Porsche recommends seat belt usage and observance of traffic laws at all times.

©2016 Porsche Cars North America, Inc.

