

Service Bulletin

File in Section:

Bulletin No.: 16-NA-100

Date: June, 2016

TECHNICAL

Subject: Fuel Tank is Hard to Fill

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
Dianu:		from	to	from	to		
Chevrolet	Silverado LD						
Chevrolet	Silverado LD Crew						
Chevrolet	Silverado LD Crew LTZ	2016	2016	October 1, 2015	January 11,2016		
Chevrolet	Silverado LD Ext						
Chevrolet	Silverado LD Ext LTZ						
Chevrolet	Silverado LD Reg						
GMC	Sierra LD Crew						
GMC	Sierra LD Crew Denali						
GMC	Sierra LD Ext						
GMC	Sierra LD Ext Denali						
GMC	Sierra LD Reg						

Involved Region or Country	North America and N.A. Export Models		
Condition	Some customers may comment that the gas tank is hard to fill.		
Cause	This condition may be due to the mold flashing issue on the check valve internal to the fuel tank.		

Correction

Refer to Poor Fuel Fill Quality for diagnosis in SI. If SI diagnostic does not isolate the root cause, replace the fuel tank.

Service Procedure

Refer to Fuel Tank Replacement in SI.

Parts Information

Refer to the electronic parts catalog (EPC).

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4029250	Fuel Tank Replacement	Use Published Labor Operation Time

Page 2 June, 2016 Bulletin No.: 16-NA-100

Version	2
Modified	June 14, 2016 – Removing 2015 MY and adding 2016 MY.