



# Service Bulletin

File in Section: -


Bulletin No.: 16-NA-185

Date: June, 2016

## INFORMATION

**Subject:** Information on Front Lower Air Dam


Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Cascada	2016	2016			All	All

<b>Condition</b>	The two piece front lower air dams are placed in the vehicles trunk at the assembly plant and installed at the dealership during PDI. They were originally separate left and right side parts, but dealers will begin seeing the two halves connected.
<b>Cause</b>	 <p>4498061</p> <p>As an error-proofing measure to ensure the left and right halves arrive properly, the two pieces now are attached to each other.</p>

### Correction

Before installation of the air dam, it will now be necessary to cut the two halves apart, removing the excess plastic.

## Service Procedure



4498064

Using scissors, or a similar cutting tool, cut the six flat tabs at the part edge and trim any excess plastic as close to the edge as possible.

## Bulletin Information

Version	1
Modified	