

No.: 16 TS-14

August 8, 2016

TO: Service Locations

FROM: Service Systems Development

SUBJECT: **EPA10 and GHG14 Service Replacement 1-BOX DOC Inlet Change**

ISSUE

Starting with ATS serial number 12400004909082, all new EPA10 and GHG14 service replacement 1-BOX will change to the new GHG17 DOC inlet flange. The original design was a cast flange while the new design is a formed flange.



Figure 1 – Original DOC Inlet Flange



Figure 2 - New DOC Inlet Flange

REQUIRED ACTION

In the event a service replacement 1-BOX is required, install the replacement, following standard procedures, regardless of which flange is found. The flanges are interchangeable, so existing piping, along with standard clamps and gaskets will be used.

CONTACT INFORMATION

Please contact the Detroit™ Customer Support Center at 800-445-1980 or email csc@daimler.com if you have any questions.