



Service Bulletin

PRELIMINARY INFORMATION

Subject: SES Light Is On With P05CE At Very Low Mileage

Attention:

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2017	2017	SOP	Current	3.6 LLT	All
Chevrolet	Equinox, Impala, Traverse	2017	2017	SOP	Current	3.6 LFX	All
GMC	Terrain	2017	2017	SOP	Current	3.6 LFX	All

Involved Region or Country	North America
Additional RPO/s:	N/A
Condition	MIL may come on with a P05CE stored in current or history with VERY low miles.
Cause	The cause for this is under investigation by engineering.

Correction

Clear code and test drive vehicle to ensure code does not return.

If code is gone then release vehicle back to the customer or sales department.

If code returns, follow eSI service procedures to diagnose and correct concern.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION