



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** 2-Mode (Hybrid) TAC APM Part Restriction has ended

**Models:** 2009 - 2013 Cadillac Escalade Hybrid  
2008 - 2013 Chevrolet Tahoe Hybrid, Silverado Hybrid  
2009 - 2013 GMC Sierra Hybrid, Yukon Hybrid  
All Models above with RPO HP2

*This PI was superseded to update Condition/Concern. Please discard PIT5338.*

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

The Part Restriction for the for the Accessory DC Power Control Module and the Seal Kit has ended.

Thank you for your assistance in collecting data.

**Important:** Special Coverage 14262 may apply

### Recommendation/Instructions

Accessory DC Power Control Module P/N 24251562 and Seal Kit P/N 19207978 can now be ordered directly through your parts department without TAC authorization.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION