

[Next Unread Message](#)**View Message**

Sent on	04	22	2016	Expires on	04	27	2016
From	Parts and Service Division						
Subject	Request for Parts: 2015 TLX Electronic Parking Brake (EPB) Actuator Inop						

PRIORITY/ACTION REQUIRED

To: All Acura Service Managers/Consultants
From: Technical Research & Support Group
RE: Request for Parts: 2015 TLX Electronic Parking Brake (EPB) Actuator Inop

Print this i/M message and provide a copy to the Shop Foreman and all Service Consultants.

Background

American Honda (AHM) is investigating certain 2015 TLXs with a client reporting on ignition start, the Electronic Parking Brake (EPB) will not release causing one or both rear wheels not to move and/or "Check Parking Brake" warning message displays in MID. To fully understand the cause of this occurrence, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

Qualifiers

1. One or more of these EPB related DTCs may be set: C1100, C1110, C1111 or C1120.
2. Troubleshooting leads technician to replace the EPB Actuator.
3. No previous repairs.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.