

Creaking from the B-Pillar

AFFECTED VEHICLES

2014–16 Odyssey

Are you hearing a creak from the base of the B-pillar when driving on uneven surfaces or when accelerating or braking? This noise may be caused by a sheet metal touch point in the base of the B-pillar.

We're currently working on a service bulletin with troubleshooting and repair info, so **do not** send the vehicle out to a body shop for repairs. Instead, go to the Tech Line landing page on the iN, select **Top Issues**, then **Odyssey "B" Pillar Creak Repair**. You'll find an illustrated repair procedure. There's no need to contact Tech Line.