

Steering Wheel Pops or Clicks When Turning After Doing S/B 16-024

AFFECTED VEHICLES

2015–16 Odyssey

Does the steering wheel continue to pop or click when turning **after** doing S/B 16-024, *Popping or Clicking When Turning the Steering Wheel*? We're aware of this concern and have confirmed that the countermeasures taken to eliminate the contamination causing this noise weren't effective.

Honda parts stock may include steering columns with contaminated bearings and currently there's no set time frame for a parts stock exchange to guarantee service parts are contamination free. If the replacement steering column you receive makes noise, we recommend replacing it again since the chances of another failure are very low.