



July 2016

BTS 160706 Version 1

EPS System Indicator Is On and Steering Is Stiff

AFFECTED VEHICLES

2014–15 MDX

If the EPS System indicator is on and the steering is stiff, the cause could be related to a poor connection. To properly troubleshoot this concern, you need to check the EPS system for DTCs. If normal troubleshooting doesn't resolve this concern, you should then contact Tech Line.

© 2016 American Honda Motor Co., Inc. – All Rights Reserved