

AWD Indicator Comes On and Stays On

AFFECTED VEHICLES

2017 Ridgeline with AWD

We're getting reports of the AWD indicator coming on and staying on. From their basic checks, service techs are noticing corrosion or moisture in connector **C601** of the rear subframe subharness.

We're aware of this issue and have it currently under investigation. We're anticipating a service bulletin in the near future.

In the meantime, contact Tech Line for the latest repair info.