

Thumping or Flapping from the Rear of the Vehicle

AFFECTED VEHICLES

2016 Accord Sedan

Are you hearing a thumping or flapping from the rear of the vehicle when the fan is set to high speed and the climate control system is in recirculation mode? The noise is being generated by the door on the cabin vent that's located behind the left rear bumper.

We're currently reviewing this concern and are looking for a solution, so **do not** replace any components at this time. We'll let you know when we have a solution available.