

APPLICABLE VEHICLES

2013-2016 FR-S

CONDITION

Customer may complain about an oil leak from the bottom of the oil pan. After a closer inspection you may find the leak is coming from the oil drain plug itself.

RECOMMENDATIONS

Replace the oil drain plug and torque to correct specification.



Torque: 42 N.m (425)

42 N·m {425 kgf·cm, 31ft·lbf}

LINK REFERENCES

1. <u>FA20 LUBRICATION: OIL AND OIL FILTER: REPLACEMENT; 2013 MY FR-S [03/2012 - ???????]</u>

Expires On

07/18/2017

© 2016, Toyota Motor Sales, USA