



# Service Bulletin

File in Section: -

Bulletin No.: 16-NA-197

Date: June, 2016

## INFORMATION

**Subject: Diagnostic Tip for Sunroof Glass and/or Sunroof Sunshade Inoperative**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu (VIN Z)	2016	2016				

<b>Involved Region or Country</b>	North America and Israel
<b>Condition</b>	Some customers may comment that the sunroof glass and/or sunroof sunshade is inoperative.

### Correction

Inspect the sunroof wiring harness for a possible loose connection by wiggling the harness while operating the sunroof motor. If the sunroof motor cuts off while wiggling the harness, repair the sunroof wiring harness. If all of the sunroof motor functions work properly, pursue with further diagnostics in SI.

<b>Version</b>	1
<b>Modified</b>	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION