

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS4082
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 22, 2016

Subject: Stop Delivery Order - GM Reference # 53940

Models: 2014-2016 Chevrolet Sonic RS

To: All Chevrolet Dealers

STOP DELIVERY ORDER

Effective immediately, stop the delivery of certain 2014-2016 model year Chevrolet Sonic RS vehicles in new vehicle inventory. The GM reference number is 53940.

GM discovered an error which affected the fuel economy information on the fuel economy labels on the 2014-2016 model year Sonic RS vehicles with manual transmissions. The error caused the EPA estimated fuel economy to be listed on the window label as 1 MPG higher (0.1L/100 KM lower) than it should have been. GM is stopping sale of the affected models until a corrected label is printed and affixed. GM will contact owners of the affected models to address this situation. This label error has no effect on the safety and operation of the vehicles.

Effective immediately, dealers must hold and may not sell or display for sale the involved vehicles until corrected Monroney (fuel economy) window labels are received and affixed to the vehicle.

Until further instructions are received, involved new vehicles that are in dealers' possession must be held and not displayed for sale, delivered to customers, or dealer-traded until a corrected window label is affixed to the vehicle.

The Investigate Vehicle History (IVH) screen in the Global Warranty Management (GWM) system will be updated for this stop delivery on June 22, 2016. This action has been taken to assist dealers with determining which vehicles are involved so they can properly respond to customer inquiries.

A list of involved vehicles that have been identified as being in dealer new vehicle inventory is attached to this message. It is sorted by dealer Business Associate Code (BAC) for easy reference. Your dealership's BAC will not be listed if none of the involved vehicles are currently in your new vehicle inventory.

We are working to obtain replacement labels and will send them to dealers as quickly as possible. When replacement labels are available, they will be released with further instructions.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS