

To: All Subaru Retailers From: Subaru of America, Inc. Date: February 24, 2016

FlashWrite Reprogramming File New CID Display Inconsistency

Due to a FlashWrite database error, when searching for 2015 Forester 2.0L Turbo pack files by Vehicle specification (only), the New CID for the latest pak files displays incorrectly as shown below. The actual New CID should read as LF61700B as shown when the search is performed using the vehicle CID#.

Regardless of how the pak file is searched, the correct file is applied by FlashWrite in both cases. If the ECM is checked following programming, the New CID LF61700B will be found as long as FlashWrite (Release Month Jan 2016) is used for this application.

This display error will be corrected as part of a future release of SSM4/ FlashWrite.

0	ption									
	Search Condition: —	Search Resu	lt							
		Pack Number	Year	Vehicle Line	Emission spec	Engine	Aspiration	Transmission	CPU	
	Vehicle spec.	22765AG974	2015	Forester	FED, CAL	2.0L	Turbo	CVT	ECM	
	CID # Entry is Case Sensitive									
	Vehicle Spec.									
	2015 🔹									
	Forester									
	2.0L -									
	Turbo 🔹	Details Print Continue								
		Update(s) for <service campaign="" wqw-58=""> Improvement of knock control, P0300, P0420, P0606 (Release Month: Jan, 2016)</service>								
	Search	Necessary connector : None								
	Clear Selection	Decryption keyword : 77149A9C								
		SUM value : —								
	New data install from CD.	New CID : LF61600B								
	nom ob.	Notes : Refer to Campaign Bulletin WQW-58 for detail information and procedure.								
	<u>G</u> 0		-anpu	gn Bailean tratt 30 loi deidir miorn	ialion and procee					

Fig 1- New CID displays incorrectly when searched by vehicle specification

0	Option										
	- Search Condition: — ⊽ CID	Search Result									
		Pack Number		Vehicle Line		Emission spec			Transmission	CPU	
	Vehicle spec.	22765AG974	2015	Forester		FED, CAL	2.0L	Turbo	сут	ECM	
	CID # Entry is Case Sensitive										
	LF61600B										
	Vehicle Spec.										
	CPU 🚽										
	Madal Xaar										
	Model Year										
	Vehicle Line 🔄										
	Engine 🔹										
	Aspiration	Details Print Continue									
		Update(s) for: <service campaign="" wqw-58=""> (Release Month: Jan, 2016)</service>									
	Search										
		nivecessary connector . None									
	<u>Clear Selection</u>	Decryption keyword : 77149A9C									
	New data install from CD.	SUM value :									
		New CID : LF617()0B								
	<u>G</u> 0	Notes : Refer to Campaign Bulletin WQW-58 for detail information and procedure.									

Fig 2- New CID displays correctly. Note that Pack Number 22765AG974 is the same as in Fig 1.