

|              |   |
|--------------|---|
| SSM<br>45875 | Some 2013-2016 Fusion vehicles equipped with ebony/piano black window switch bezels may exhibit a warped bezel that does not sit flush. Replace the effected window switch bezel. Refer to the following updated part numbers for bezel replacement: GS7Z-14527-BA → Front Right, GS7Z-14528-AA → Front Left, GS7Z-14527-BB → Rear Right, GS7Z-14528-BA → Rear Left. Refer to Workshop Manual, Section 501-11 for front door window control switch and rear door window control switch removal and installation procedure. Use causal component 14527 and refer to section 12 of the Service Labor Time Standards manual. |
|--------------|---|