

SSM 45876	Some 2016-2017 F-53 Motorhome Chassis and F-59 Commercial Stripped Chassis vehicles equipped with a 6.8L engine and a GVWR of 14,001 lb through 19,500 lb (4th digit of VIN is 4 or 5) may not downshift when going downhill when in Tow-Haul mode. Engineering is aware of this condition and is investigating. No repairs should be attempted at this time. Monitor OASIS for future updates.
--------------	---