

SSM 45900	If a 2011-2016 F-Super Duty with optional running boards, is operated off-road or in low ground clearance conditions, the running board attachment points on the lower cab floor side sill member may be damaged. The customer may notice that the running boards are loose or sagging as an indication of the concern. A lower cab floor side sill member repair kit is available part number BC3Z-9910120-A, to aid in this repair. Follow service kit instructions and WSM Section 501-35 for repairs. Note: If there is damage to the running board(s) or the lower cab floor side sill member, this repair may be non-warrantable. Refer to warranty policy manual for coverage.
--------------	---