

Technical Service Bulletin

SUBJECT: TSB-16-52A-002 No: SRS WARNING ADDED TO FRONT SEAT June, 2016 DATE: **REMOVAL & INSTALLATION PROCEDURE -**MODEL: 2011-15 Outlander SERVICE MANUAL REVISION Sport/RVR [] GENERAL MANAGER **CIRCULATE TO:** [X] PARTS MANAGER [X] TECHNICIAN [X] SERVICE ADVISOR [X] SERVICE MANAGER [] WARRANTY PROCESSOR [] SALES MANAGER

PURPOSE

This TSB updates the Interior section of the affected Service Manuals to add a warning to check occupant classification sensor accuracy during front seat removal and installation.

AFFECTED VEHICLES

2011–2015 Outlander Sport/RVR

AFFECTED SERVICE MANUALS


2011-2015 Outlander Sport/RVR Service Manual, Group 52A - Interior



Please make the indicated changes to the 2011 – 2015 Outlander Sport/RVR Service Manual, Group 52A – Interior –> Seat Assembly -> Front Seat Assembly -> Removal and Installation.

INTERIOR MIRROR

INTERIOR MIRROR




REMOVAL SERVICE POINT

- 1. Disengage the claw A and lower the cover toward arrow 1 direction.
- 2. Push the claw B toward arrow 2 direction to unlock, and pull out the mirror toward arrow 3 direction.

SEAT ASSEMBLY

FRONT SEAT ASSEMBLY REMOVAL AND INSTALLATION



AWARNING

When removing and installing the front passenger seat, be sure to carry out accuracy check of occupant classification sensor after the seat has been installed in the vehicle (Refer to GROUP 52B, On- vehicle service).