



Service Bulletin

INFORMATION

Subject: Engineering Information – Accessory Wheel Flare Warping or Accessory Wheel Flare Tape Separating

Models: 2015-2016 Chevrolet Colorado
2015-2016 GMC Canyon
Equipped with Accessory Wheel Flares (RPO-SF5)

This PI has been revised to end the need for information from the field. Please discard PIE0358.

If you encounter a vehicle with this concern, please refer to the following information:

- October 2015 Emerging Issues video link: Course number 10215.10D found in Center Of Learning - <https://www.centerlearning.com/HomePage/Portal.asp>
- Accessory installation instruction sheet – SI Document ID: 4093205

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION