

Service Bulletin

PRELIMINARY INFORMATION

Subject: SES Lamp On With DTC P151E

Models:	2015 Chevrolet Colorado
	2015 GMC Canyon
	Equipped with 3.6L Engine (RPO LFX)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The SES lamp may be on with both DTC P151E and P069E stored. Depending on the powertrain configuration the P151E may be stored in either the Engine Control Module (ECM) or the Fuel Pump Control Module (FPCM) (aka Chassis Control Module).

Recommendation/Instructions

Important: This concern does NOT involve the DTC P059F. Do NOT replace parts for DTC P059F as this DTC is often an indicator of obstruction in the shutter such as ice or snow.

Engineering is aware of the concern with P151E and working toward a permanent solution. Please contact GM Technical Assistance for further support

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

