



Service Bulletin

PRELIMINARY INFORMATION

Subject: SES Light - Service Front View Camera Module Message - Other Various Electrical Concerns

Models: 2016 Chevrolet Malibu (VIN Z)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may comment on one or more of the following.

- SES light on dim when the vehicle is running
- SES light on dim when the vehicle is put into gear
- SES light on dim when locking or unlocking the doors
- Service Front View Camera Module Message on in the DIC
- Other various electrical concerns

When checking the vehicle for codes, DTCs may or may not be found

Recommendation/Instructions

Inspect connector X210 for bent terminals.

Warranty Information

For wiring repairs covered under warranty, please refer to latest version of bulletin 10-00-89-005 for warranty information on wire/connector repairs.

Additional SI Keywords:

U2098

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION